ENG.JITENDERA KUMAR Lalgange Nagar Parishad)

Reg. No:- 04/2015

Adders-Ma.Bhagbati complex Cinema road Hajipur M.No-9931908471

BUILDING SAFETY CERTIFICATE

(To Whom It May Concern)

This to certify that the School building of GURU VASHISHTHA VIDYAYAN AT – Ma Durga nagar (PANAPUR BORDER CHAKSAKRA) hajipur P.O.- Hajipur ,P.S. hajipur sadar Distt. Vaishali,844101

,Bihar,Survey Plot no.89,90,163,164,167&169

Khata no.05, Thana no-114,115, at MA DURGA NAGAR HAJIPUR, District: Vaishali. Structural design and planning of the building prepared by this consultants. This building Has been constructed as per the norms of Bureau of standards for building construction. The school is RCC column with framed structure building, Life span -90 years and above. There is ample provision for fire and earthquake safety.

The school has good sanitary conditions and electrical work as per norms stated by CBSE. The school has provided sufficient toilets and urinals for both boys and girls.

The school has its own boring with motor /pump set and overhead tank to comfortably Meet the needs of the students. It has provided sufficient drinking water facilities for the Students.

To meet the necessity of electricity the school has its own 60 KVA generator, Lift Etc. The classrooms are will ventilated and illuminated, with sufficient fans in each class rooms.

Rocke Skyam Sz'ngh Chairman Chairman Guru Vashishtha Vidyayan Hajipur, Vaishali